DVE 8031/8032
TECHNICAL SERVICE BULLETIN #1

Status: **Mandatory Field Corrective Action**

Product: DVE 8031 / 8032

Date: March 4, 2002

Reference Doc: 09.01 Deiluweit No.: 5 released on 9/5/01

Re: Installation of G15381- Conversion Kit DVE 803x

Reason/Rational: Draeger Medical has released a hardware modification to increase the vertical stability of the pendant head or pendant column.

Solution/Procedure: Install part number G15381- "Conversion Kit DVE 803x". Refer to Service Procedure SP00239. See "Additional Info", below.

Devices affected: Ceiling Supply Units DVE 8031/ 8032 up to serial number ARND-0235 (prior to May 1999), **without** combination of adjusting nut G15644 and threaded bushing / nut assembly G15643.



Diagram for reference only

Timing/When: Next inspection or repair, but no later than August 2002.

DrägerService
3122 Commerce Drive
Telford, PA 18969
Tel: (215) 721-5402
(800) 543-5047
Fax: (215) 723-5935
Web: www.draegermedical.com

Additional Info: Installation instructions can be found under SP00239, located in the Service Procedures database on Lotus Notes.

Cost: Costs to be captured using DragerService Dispatch system, under job type ” Architectural Rework - No Charge”. An invoice will be sent to DMT upon completion of this rework, to the attention of Mr. Förster-Adler, cost center 7500. Parts to be provided free of charge, until requested completion date of August 2002.

Ordering Info/Parts: Order part number **G 15381- “Conversion Kit- DVE 803x”**. Please contact your customer service representative to place a no charge sales order.

Distribution: DragerService (direct)

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-723-5935.

DrägerService
3122 Commerce Drive
Telford, PA 18969
Tel: (215) 721-5402
(800) 543-5047
Fax: (215) 723-5935
Web: www.draegermedical.com